

**Checking of quality and gradient of drains in Gandhi Nagar area and Gajapati Nagar area for the work done in the year 2018-19.**

As per the order of the Commissioner vide letter No. 13049. Dated 24.09.2019, the list of the work done in past one year has been collected from the concerned Engineers of BeMC and the gradient of drains and the quality of Drains & Road have been assessed as follows:

**Gandhi Nagar Area:**

| Sl No | Name of work   | Estimated cost | Slope/Gradient of drains   | Quality of work | Remarks   |
|-------|--|----------------|--|-----------------|-----------|
| 1     | Repair and restoration of drain at Gandhi Nagar 3 <sup>rd</sup> line backside of Aswini choudhury Res. In ward no.23   | 5,00,000/-     | Verified with level instrument and found good  | Good            | Completed |
| 2     | Construction of C.C drain & culvert at Gandhi Nagar 3 <sup>rd</sup> & 4 <sup>th</sup> line Ext. In w.No.23   | 7,10,000/-     | Verified with level instrument and found that the drain bed level filled of with silts. Desilting required | Good            | Completed |
| 3     | Construction of C.C Road at Gandhi Nagar 1 <sup>st</sup> , 3 <sup>rd</sup> and canal street drain 1 <sup>st</sup> line in w.no.23                                    | 10,84,000/-    | Verified with level instrument and found that the drain bed level filled of with silts. Desilting required | Good            | Completed |
| 4     | Const. Of C.C Drain & culvert at Gandhi Nagar 7 <sup>th</sup> lane main road side back side of 7 <sup>th</sup> line & 5 <sup>th</sup> Ext. Near Lalita Sahu w.no.23. | 23,62,000/-    | Verified with level instrument and found that the drain bed level filled of with silts. Desilting required | Good            | Completed |
| 5     | Construction of C.C Drain & culvert of 6 <sup>th</sup> line back side of Spectrum Colony in w.no.23  | 8,44,000/-     | Verified with level instrument and found good  | Good            | Completed |
| 6     | Repair of C.C Drain & culvert of back side of Parmajyoti Hall in w.no.23   | 1,99,000/-     | Verified with level instrument and found good  | Good            | Completed |
| 7     | Construction of C.C Drain at Sai Complex Gandhi Nagar main road and Gandhi Nagar 5 <sup>th</sup> line Spectrum Colony ( Senior citizen)                              |                | Verified with level instrument and found good  | Good            | Completed |

*[Handwritten signature]*  
27/11/19

*[Handwritten signature]*  
31/10/2019

**Gajapati Nagar:**

| Sl No | Name of work   | Estimated cost | Slope/Gradient of drains   | Quality of work | Remarks   |
|-------|--|----------------|--|-----------------|---|
| 1     | Improvement of Road & Drain at Gajapati Nagar 10 <sup>th</sup> & 12 <sup>th</sup> lane in w.no.33  | 20,00,000/-    | Verified with level instrument and found good  | Good            | Completed   |
| 2     | Imp.of road with drain at Gajapati Nagar 11 <sup>th</sup> line ext. Ward no.33   | 8,50,000/-     | Verified with level instrument and found good  | Good            | Completed   |
| 3     | Construction of Drain in E.W.S Colony from 6 <sup>th</sup> lane to 9 <sup>th</sup> lane and road from 9 <sup>th</sup> lane to 10 <sup>th</sup> lane in E.W.S Colony ward no 33.  | 12,75,000/-    | Verified with level instrument and found good  | Good            | Completed   |
| 4     | Const. Of drain at Gajapati Nagar 8 <sup>th</sup> line in ward no.33   | 11,00,000/-    | Verified with level instrument and found good  | Good            | Completed   |
| 5     | Const. Of C.C Road & both side drain at Gajapati Nagar 12 <sup>th</sup> line leading to Bidyutpuri Colony in w.no.33   | 10,00,000/-    | Verified with level instrument and found that the drain bed level filled of with silts. Desilting required |                 | Due to disruption of construction for encroachment water logging occurs. The junior engineer has been advised to complete construction of drain continuously to avoid water logging at that locality. |
| 6     | Construction of Drain at Gajapati Nagar 12 <sup>th</sup> back side of Chandramani Tripathy Res. Renovation of drain at Gajapati Nagar 6 <sup>th</sup> lane, Sidharth Nagar 4 <sup>th</sup> lane to 1 <sup>st</sup> lane with 3 nos. Of culvert & Sidharth Nagar 3 <sup>rd</sup> lane main road to Dinabandhu Bhaban ward no.33 | 30,65,000/-    | Verified with level instrument and found good  | Good            | Completed   |
| 7     | Construction of C.C Drain in 7 <sup>th</sup> lane in Gajapati Nagar wards no.33.   | 18,37,700/-    | Verified with level instrument and found good  | Good            | Completed   |

  
Project Officer/ODRP,  
BeMC, Berhampur

  
3/10/2019  
City Engineer  
BeMC, Berhampur